

Step 1



Keep the hat in room temperature before using.

If you're outside during colder days it will take more time for the hat to adjust to the head.

Step 2



Put it on while velcro is open, then adjust as needed to provide the best possible fit.

Keep in mind that the padding might feel hard and stiff at first. Just wait for the miracle...

Step 3

1-2 minutes



Allow up to 1-2 minutes for the padding to become softer.

The hat will react from body's temperature and take its form around the head.

Step 4



Enjoy the comfort and protection PADHAT provides!

The hat will take its form around the head and feel like its custom made.